

Installing a 3/8" plate between the tabs and the track bar riser will position the ram cylinder more in line with the tie rod.
View looking from driver side wheel well opening.
Tie rod and cylinder ram not parallel.